

Michael Furtaw

From: LaRue, Sam <Sam.LaRue@anadarko.com>
Sent: Friday, January 15, 2016 11:09 AM
To: 'Gintautas - DNR, Peter'; 'Roy Rudisill'; 'tswain@weldgov.com'; 'Tom Parko'; Ellice Hazard - DNR
Cc: Schneider, Paul; Chase, Charles; Dinkel, Mike; Rowley, Taylor [Arcadis US, Inc.]; Schwarz, Paul; Hamlin, Phil; Mickelson, Erik; Rothermel, Margaret [LT Environmental]; John Cocroft; Justin Solomon; Kristofer Shepherd; Ryan Zernis; Andy Verbonitz; Michael Furtaw
Subject: Spill Notification - HSR-Rademacher-63N67W

Good Morning,

We had a State Reportable Release at the location listed below. The release appears to originate from a hole caused by corrosion in an oil bypass line. Results from a shallow groundwater sample were received on January 15, 2016 and indicated that the sample exceeded COGCC Table 910-1 concentration levels. Further information will be provided in a forthcoming Form 19 Initial Release Report.

HSR-Rademacher-63N67W
Location ID: 336118
SESW-30-3N-67W

[Sam LaRue](#) | Sr. HSE Representative
Anadarko Petroleum Corporation | 501 N. Division Blvd. | Platteville, CO 80651
Direct: 970-515-1238



[Click here for Anadarko's Electronic Mail Disclaimer](#)