



Observation Report)

COGCC Results

Ursa: Watson Ranch B 24AWI-17-07-95
API: 045-22801
O&G and Water Wells 1/4-Mile

Selected Items Report

Oil and Gas Wells Selected

Red rectangles mean well
is on Ursa map

by Formation

Include

N-COM
WFCM
WMFK

Filter

WELL DESCRIPTION	LOCATION ID	LOCATION	WELL INFORMATION
05-045-18713, BAT 22D-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7150 WFCM PR
05-045-18714, BAT 23D17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6625 WFCM PR
05-045-18715, BAT 24B-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6568 WFCM PR
05-045-19066, BAT 34D-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7015 WFCM PR
05-045-19067, BAT 14D-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6645 WFCM PR
05-045-19070, BAT 13C-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status AL
05-045-19074, BAT 14A-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	see 045-20539=same name Surf in Section18=PR Status AL
05-045-19082, BAT 24D-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6634 WFCM PR
05-045-19089, BAT 44A-18-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7051 WFCM PR
05-045-19092, WATSON RANCH B 23A-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6930 WFCM PR
05-045-19093, BAT 13A-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status AL
05-045-19095, BAT 23B-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6750 WFCM PR
05-045-19098, BAT 13D-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6662 WFCM PR
05-045-19100, WATSON RANCH B 23C-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6686 WFCM PR
05-045-19101, BAT 34B-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7001 WFCM PR
05-045-19106, BAT 14C-17-07-95 URSA OPERATING COMPANY LLC	413055	SESW 17	see 045-20527=same name Surf in Section18=PR Status AL

URSA OPERATING COMPANY LLC	159652	7S -95W (6)	AL
05-045-19108. BAT 13B-17-07-95. URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6782 WFCM PR
05-045-19109. BAT 14B-17-07-95. URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6580 WFCM PR
05-045-19719. WATSON RANCH B 24C-17-07-95. URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6600 N-COM WO 00 6600 WFCM PR
05-045-19721. WATSON RANCH B 24A-17-07-95. URSA OPERATING COMPANY LLC	413055	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6589 N-COM PR 00 6589 WFCM PR
05-045-22748. YATER 21C-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22749. YATER 21D-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22750. YATER 43C-18-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6890 N-COM PR 00 6890 WFCM PR
05-045-22752. YATER 11D-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22753. YATER 22C-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6960 WMFK PR
05-045-22757. YATER 42D-18-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7111 WFCM PR
05-045-22758. YATER 22B-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22759. YATER 11C-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22761. YATER 12D-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6856 WMFK PR
05-045-22763. YATER 43A-18-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7025 WFCM PR
05-045-22768. YATER 43B-18-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6970 N-COM PR 00 6970 WFCM PR
05-045-22772. YATER 12C-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6969 WFCM PR
05-045-22775. YATER 22A-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22779. YATER 12A-17-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22781. YATER 43D-18-07-95. URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6885 N-COM PR 00 6885 WFCM PR

05-045-22784, YATER 12B-17-07-95 URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22799, WATSON RANCH B 32C-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7356 N-COM PR 00 7356 WFCM PR
05-045-22800, WATSON RANCH B 33A-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7180 N-COM PR 00 7180 WFCM PR
05-045-22801, WATSON RANCH B 24AWI-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM SI
05-045-22802, WATSON RANCH B 33C-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6995 N-COM PR 00 6995 WFCM PR
05-045-22803, WATSON RANCH B 32B-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7497 N-COM PR 00 7497 WFCM PR
05-045-22804, WATSON RANCH B 32D-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7298 N-COM WO 00 7298 WFCM PR
05-045-22805, WATSON RANCH B 34C-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6856 N-COM PR 00 6856 WFCM PR
05-045-22806, WATSON RANCH B 33D-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6935 N-COM PR 00 6935 WFCM PR
05-045-22807, WATSON RANCH B 34A-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 6881 N-COM PR 00 6881 WFCM PR
05-045-22808, WATSON RANCH B 33B-17-07-95 URSA OPERATING COMPANY LLC	440705	SESW 17 7S -95W (6)	Sidetrack TD Formation Status 00 7045 N-COM PR 00 7045 WFCM PR
05-045-22824, YATER 42A-18-07-95 URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22825, YATER 11B-17-07-95 URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22826, YATER 42C-18-07-95 URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22827, YATER 42B-18-07-95 URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR
05-045-22828, YATER 41D-18-07-95 URSA OPERATING COMPANY LLC	159652	NWSW 17 7S -95W (6)	Sidetrack TD Formation Status 00 N-COM PR

Water Wells Selected From Map

Filter Results by Depth		Greater than	<div></div>	Filter	
WELL DESCRIPTION	LOCATION	WELL INFORMATION			
		Depth	Top Perf	Bottom Perf	Aquifer
Receipt=0111457. Permit=0008517-AD- GARDNER GEORGE R.	SESW 17 7 S-95W	0	0	0	GW
Receipt=0410961. Permit=0201614-- RIVELLI BARBARA LOU	SESW 17 7 S-95W	100	60	100	GW
Receipt=9500565. Permit=0051470-F-R ALLRED BARBARA L	SESW 17 7 S-95W	148	105	148	GW
Receipt=9114497. Permit=0095280-- LEUALLEN KEVIN S & TAMMY A	NENW 20 7 S-95W	145	105	145	GW

Receipt=0435735A, Permit=211946 Wehr Gant Lena Estate of	SWSW 17 7 S-95W	120	50	120	GW
---	--------------------	-----	----	-----	----

Oops, missed one.

Ursa: Watson Ranch B 24AWI-17-07-95 1/4-Mile Wells Selected

