

Document Number:
 401027420
 Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: DOREEN GREEN
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (435) 781-9758
 Address: P O BOX 173779 Fax: _____
 City: DENVER State: CO Zip: 80217- Email: DOREEN.GREEN@ANADARKO.COM

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____
COGCC contact:

API Number 05-123-16567-00
 Well Name: BLUFFS WHITE W Well Number: 5-1
 Location: QtrQtr: NENE Section: 5 Township: 2N Range: 66W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.172455 Longitude: -104.794033
 GPS Data:
 Date of Measurement: 06/17/2008 PDOP Reading: 3.4 GPS Instrument Operator's Name: Renee Doiron
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
SUSSEX	4595	4613	03/01/2016	CEMENT	3292
CODELL	7352	7362	02/22/2016	B PLUG CEMENT TOP	7311

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	540	370	540	0	VISU
1ST	7+7/8	3+1/2	9.3	7,543	250	7,543	6,500	CBL
S.C. 1.1				5,252	445	5,252	4,124	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7311 with _____ sacks cmt on top. CIBP #2: Depth 80 with 41 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 7270 ft. to 6654 ft. Plug Type: CASING Plug Tagged:
 Set 35 sks cmt from 4700 ft. to 3292 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set 440 sacks half in. half out surface casing from 1320 ft. to 150 ft. Plug Tagged:
 Set 41 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1220 ft. of 3+1/2 inch casing Plugging Date: 03/17/2016
 *Wireline Contractor: FMC *Cementing Contractor: SANJEL
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

NOTE THE 20 SX PUMPED ON TOP OF CIBP @ 7311 NOT NOTED IN WELLBORE DIAGRAM AS NO RETURNS THROUGH OUT JOB AND DID NOT TAG CEMENT. 2 SX SAND WERE SPOTTED ON TOP OF THE CIBP @ 7311.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: DOREEN GREEN
 Title: REGULATORY ANALYST Date: _____ Email: RSCDJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401027426	CEMENT JOB SUMMARY
401027427	WELLBORE DIAGRAM
401027793	WIRELINER JOB SUMMARY
401028013	OPERATIONS SUMMARY

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)