

Interim Reclamation Inspection

4/25/2016

Operator: High Plains Energy

Location #: 430585

Logan County, CO

NENE Section 32 T7N R52W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken from the southwest corner of the location, facing south. Photo shows large areas of the location where revegetation is not progressing.



Figure 2: Photo taken from the southwest corner of the location, facing southeast. Photo shows large areas of the location where revegetation is not progressing.



Figure 3: Photo taken from the southwest corner of the location, facing east. Photo shows large areas of the location where revegetation is not progressing.



04.25.2016 11:35

Figure 4: Photo taken from the southwest corner of the location, facing northeast. Photo shows large areas of the location where revegetation is not progressing.



04.25.2016 11:35

Figure 5: Photo taken from the southwest corner of the location, facing north. Photo shows large areas of the location where revegetation is not progressing.



Figure 6: Photo taken from the northwest corner of the location, facing south. Photo shows large areas of the location where revegetation is not progressing.



04.25.2016 11:38

Figure 7: Photo taken from the northwest corner of the location, facing southeast. Photo shows large areas of the location where revegetation is not progressing.



Figure 8: Photo taken from the northwest corner of the location, facing east. Photo shows large areas of the location where revegetation is not progressing.



Figure 9: Photo taken from the northwest corner of the location, facing northeast. Photo shows large areas of the location where revegetation is not progressing.



Figure 10: Photo taken from well.



Figure 11: 2015 aerial imagery. Image shows size/perimeter of disturbance 1 year after location was constructed. Two growing seasons have passed at this point.



3/19/2016

Google earth

Figure 12: 2016 Aerial imagery. Image shows locations current size of disturbance compared to 2015 (red line). Note locations current area of disturbance has not been reduced in size as required by interim reclamation rules, but rather, has increased in size.