

Michael L. Brown

From: "Scott Webb" <ScottW@whiting.com>
To: <ml_brown@bresnan.net>
Sent: Monday, May 16, 2016 6:55 AM
Subject: FW: SIDETRACK REQUEST FOR HORSETAIL 08C-1708 – API 05-123-42850-00

From: Burn - DNR, Diana [mailto:diana.burn@state.co.us]
Sent: Sunday, May 15, 2016 1:25 PM
To: Chad Anton
Cc: Cole Orley; Peggy Butler; Chad Fitzgerald; Unit 409; John Masenheimer; Scott Webb; Barbara Westerdale; Dirk Sutphin; Garrison, Penny
Subject: Re: SIDETRACK REQUEST FOR HORSETAIL 08C-1708 – API 05-123-42850-00

Please proceed as proposed.

Thanks,
Diana

On May 14, 2016 6:29 PM, "Chad Anton" <chad.anton@whiting.com> wrote:
SIDETRACK REQUEST
HORSETAIL 08C-1708 – API 05-123-42850-00
PROPOSED OR COMPLETED OPERATIONS:

Diana,

We have drilled most of the lateral out of our desired target formation. We would like to open hole sidetrack the lateral to re-drill the lateral in our target formation. Please let me know if you have any questions.

Thanks,
Chad

- **TOTAL DEPTH REACHED:**
- 13,353' (MD) 5,766' (TVD)
- **CASING:**
- SURFACE CASING:
- SIZE 9-5/8" 36PPF J-55 LTC
- DEPTH 2,020'
- **DESCRIPTION OF FISH IN THE HOLE:**
- NO FISH TO REPORT
- **PLUG BACK DEPTH:**
- NO PLUG FOR OPENHOLE SIDETRACK
- **SIDETRACK KICK OFF POINT:**
- 8,060' (MD), 5,823' (TVD)
- **BHL TARGET FOR SIDETRACK HOLE:**
- (SAME TARGET FORMATION NIOBRARA B) 5,750'(TVD) @ TD, 100' FSL AND 2,475'FWL S17-T10N-R57W
- **VERBAL APPROVAL TO SIDETRACK:**
- PENDING

Chad Anton

Drilling Engineer

Whiting Petroleum Corporation

and its wholly owned subsidiary

Whiting Oil and Gas Corporation

1700 Broadway, Suite 2300

Denver, CO 80290

Direct [\(303\) 876-7059](tel:3038767059)

Cell [\(303\) 570-7371](tel:3035707371)

chad.anton@whiting.com

www.whiting.com

The information contained in this message may be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by replying to this message and deleting it from your computer.