

Interim Reclamation Inspection



Photo 1. Photo taken from northern location, facing East, towards the south-facing topsoil stockpile. Per Rule 1002.c., best management practices to prevent weed establishment shall be implemented. Undesirable, weedy plant species dominates topsoil stockpile that is not protective of the topsoil stockpile.

Interim Reclamation Inspection



Photo 2. Photo taken from northern location, facing East, towards the south-facing topsoil stockpile. Per Rule 1002.c., best management practices to prevent weed establishment shall be implemented. Undesirable, weedy plant species dominates topsoil stockpile that is not protective of the topsoil stockpile.

Interim Reclamation Inspection



Photo 3. Photo taken from northern location, facing East, towards the north-facing topsoil stockpile. Per Rule 1002.c., best management practices to prevent weed establishment shall be implemented. Undesirable, weedy plant species dominates topsoil stockpile that is not protective of the topsoil stockpile.

Interim Reclamation Inspection



Photo 4. Photo taken from eastern location, facing South. Per Rule 1003.e., the area shall be treated if necessary and practicable to prevent invasion of undesirable species and noxious weeds on crop lands. Perimeter of location is dominated by undesirable plant species.

Interim Reclamation Inspection



Photo 5. Photo taken from western location, facing South. Per Rule 1003.e., the area shall be treated if necessary and practicable to prevent invasion of undesirable species and noxious weeds on crop lands. Perimeter of location is dominated by undesirable plant species.