

Battlement Mesa 34F Pad
Inspection Doc# 675203330

Interim Reclamation
View from entrance



Reconstructed drainage on
NE side of location



Reconstructed slope where
subsidence was



Re-contoured fill side of
location



Berm on fill side of location



Rock wall and drainage on cut slope side of wellheads.

