

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

10/31/2016

Document Number:

682401407**FIELD INSPECTION FORM**

Loc ID 311459	Inspector Name: Binschus, Chris	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>47120</u> Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u> Address: <u>P O BOX 173779</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>				

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264513	WELL	PR	01/11/2008	GW	123-21077	BAJA 14-35A	RI

General Comment:

This is a follow up interim reclamation inspection to FIR Document #682400843 regarding an outstanding corrective action to fix a portion of the access road on a shared tank battery location. A similar inspection report will be sent to all operators at this location. The operators may need to coordinate efforts to resolve the issue to bring the location into compliance.

Location**Lease Road:**

Type	Other		
comment:	Corrective actions from FIR Document #682400843 to fix ruts around the tank battery location have been performed. Refer to attached photos in Document #682401408.		
Corrective ActionL		Date:	
Type	Access		
comment:	Need to repair access road that was widened by an operator and return it to its original condition. Refer to attached photos in Document #682401408.		
Corrective ActionL	Repair access road and re-seed any portions that are disturbed during this process. Please coordinate with the landowner on a preferred seed mix. In the absence of an agreement between the operator and the affected surface owner as to what seed mix should be used, the operator shall consult with a representative of the local NRCS district to determine the proper seed mix to use in revegetating the disturbed area by corrective action date of 11/30/16 or sooner, if possible.	Date:	11/30/2016

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No _____

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 264513 Type: WELL API Number: 123-21077 Status: PR Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401408	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988801