

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/25/2016
Submitted Date:
10/31/2016
Document Number:
682401409

FIELD INSPECTION FORM

Loc ID 318331 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:
3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	(303) 825-4822	slaramesa@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241123	WELL	PR	10/07/1976	OW	123-08911	JACK BERGER A 5	RI

General Comment:
[This is a follow up interim reclamation inspection to FIR Document #682400845 regarding an outstanding corrective action to fix a portion of the access road on a shared tank battery location. A similar inspection report will be sent to all operators at this location. The operators may need to coordinate efforts to resolve the issue to bring the location into compliance.](#)

Location

Lease Road:			
Type	Other		
comment:	Corrective actions from FIR Document #682400845 to fix ruts around the tank battery location have been performed. Refer to attached photos in Document #682401410.		
Corrective ActionL		Date:	
Type	Access		
comment:	Need to repair access road that was widened by an operator and return it to its original condition. Refer to attached photos in Document #682401410.		
Corrective ActionL	Repair access road and re-seed any portions that are disturbed during this process. Please coordinate with the landowner on a preferred seed mix. In the absence of an agreement between the operator and the affected surface owner as to what seed mix should be used, the operator shall consult with a representative of the local NRCS district to determine the proper seed mix to use in revegetating the disturbed area by corrective action date of 11/30/16 or sooner, if possible.	Date:	11/30/2016

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 50%;" type="text"/>
Corrective Action:	<input style="width: 50%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241123 Type: WELL API Number: 123-08911 Status: PR Insp. Status: RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401410	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988802