

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

10/31/2016

Document Number:

682401407**FIELD INSPECTION FORM**
 Loc ID 311459 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num:                     
**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264513	WELL	PR	01/11/2008	GW	123-21077	BAJA 14-35A	RI

**General Comment:**

This is a follow up interim reclamation inspection to FIR Document #682400843 regarding an outstanding corrective action to fix a portion of the access road on a shared tank battery location. A similar inspection report will be sent to all operators at this location. The operators may need to coordinate efforts to resolve the issue to bring the location into compliance.

**Location**

<b>Lease Road:</b>			
Type	Other		
comment:	Corrective actions from FIR Document #682400843 to fix ruts around the tank battery location have been performed. Refer to attached photos in Document #682401408.		
Corrective ActionL		Date:	
Type	Access		
comment:	Need to repair access road that was widened by an operator and return it to its original condition. Refer to attached photos in Document #682401408.		
Corrective ActionL	Repair access road and re-seed any portions that are disturbed during this process. Please coordinate with the landowner on a preferred seed mix. In the absence of an agreement between the operator and the affected surface owner as to what seed mix should be used, the operator shall consult with a representative of the local NRCS district to determine the proper seed mix to use in revegetating the disturbed area by corrective action date of 11/30/16 or sooner, if possible.	Date:	11/30/2016

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 264513 Type: WELL API Number: 123-21077 Status: PR Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401407	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988814</a>
682401408	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988801">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988801</a>