

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2016

Submitted Date:

11/17/2016

Document Number:

678200509**FIELD INSPECTION FORM**
 Loc ID 317102 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|--------------------------|---------|
| Axelson, John | | john.axelson@state.co.us | |
| Rebol, Dave | | daverebol@hotmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|---------|----------------------|-------------|
| 107667 | PIT | AC | | | - | CHM TANK BATTERY PIT | EI |
| 107668 | PIT | AC | | | - | CHM TANK BATTERY PIT | EI |

General Comment:

Environmental Inspection. Produced water pit (west) berms adjacent to the roadside have multiple animal burrows that may threaten the pit berm integrity. Improve the pit berms to ensure produced water pit integrity. The berms around the oil skim tank should be improved to ensure adequate containment of potential spills.

| Inspected Facilities | | | | |
|----------------------|-----------|---------------|------------|------------------|
| Facility ID: 107667 | Type: PIT | API Number: - | Status: AC | Insp. Status: EI |
| | | | | |
| Facility ID: 107668 | Type: PIT | API Number: - | Status: AC | Insp. Status: EI |
| | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Extensive animal burrowing in western pit berms. Eastern pit berms are much more robust than the western berms.

Corrective Action

Maintain pit berms to ensure produced water pit integrity.Date: 12/30/2016c**Fencing:**Fencing Type: Fencing Condition: Comment:

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment:

Corrective Action

Date: **COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <u>Erosion from and animal burrows on the western produced water pit berm require improvement/BMP installation.</u> | youngr | 11/17/2016 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------------|---|
| 678200509 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005887 |
| 678200511 | Animal burrows at tank battery sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005843 |
| 678200512 | Animal burrows at treater berm | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005844 |

| | | |
|-----------|--|---|
| 678200513 | Inadequate secondary containment berms at oil skim tank | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005845 |
| 678200514 | Animal burrows and berm material erosion W side of PW pits | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005846 |
| 678200515 | Animal burrow in W produced water pit berm | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005847 |
| 678200516 | Animal burrows in W produced water pit berm | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005848 |
| 678200517 | Animal burrows in W produced water pit berm | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005849 |
| 678200518 | View S across E produced water pit berm | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005850 |