

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401166940

Date Received:
12/14/2016

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96340

Name of Operator: WIEPKING-FULLERTON ENERGY LLC

Address: 4600 S DOWNING ST

City: ENGLEWOOD State: CO Zip: 80113

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Linda Boone

Phone

(720) 271-8605

Email

ldboonepar@aol.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673503798

Inspection Date: 10/11/2016

FIR Submit Date: 10/27/2016

FIR Status: _____

Inspected Operator Information:

Company Name: WIEPKING-FULLERTON ENERGY LLC

Company Number: 96340

Address: 4600 S DOWNING ST

City: ENGLEWOOD State: CO Zip: 80113

LOCATION - Location ID: 418551

Location Name: PILGER BERGE Number: 12-7 #2 County: CHEYENNE

Qtrqr: Lot 2 Sec: 7 Twp: 13S Range: 50W Meridian: 6

Latitude: 38.932560 Longitude: -103.050860

FACILITY - API Number: 05-017-00 Facility ID: 418550

Facility Name: PILGER BERGE Number: 12-7 #2

Qtrqr: Lot 2 Sec: 7 Twp: 13S Range: 50W Meridian: 6

Latitude: 38.932560 Longitude: -103.050860

CORRECTIVE ACTIONS:

1 CA# 53719

Corrective Action: Remove the degraded hay bale debris from the location. Decompact soils by cross ripping to a depth of 18inches. Reseed the access road and location and stabilize disturbed soils to prevent erosion using a weed free mulch or equivalent method.

Date: 12/23/2016

Response: CA COMPLETED

Date of Completion: 10/30/2016

Operator Comment: Wiepking-Fullerton is submitting this Field Inspection Report Resolution (FIRR) form in response to the Corrective Actions identified in the COGCC inspection conducted on October 11, 2016 (COGCC Doc No. 673503798).

On October 30, 2016, Wiepking-Fullerton performed subsequent reclamation activities. The additional

reclamation activities included removal of debris, soil compaction alleviation by cross ripping the site to a depth of 18 inches below ground surface, applied Simplot 40-Rock fertilizer at a rate of 50 pounds per acre, seeded the location with NRCS recommended seed mix specific to the location (attached), and crimped in straw at a rate of 2,000 pounds per acre for erosion prevention.

Photos of the reclamation activities were taken on November 14, 2016 (attached).

Wiepking-Fullerton will continue to monitor the site until final reclamation objectives per COGCC Rule 1004 is acheived. Additionally, Wiepking-Fullerton will be submitting a variance request per COGCC Rule 1001.c. in response to the landowners request to keep the access road for on-going ranching operations.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Wiepking-Fullerton is submitting this Field Inspection Report Resolution (FIRR) form in response to the Corrective Actions identified in the COGCC inspection conducted on October 11, 2016 (COGCC Doc No. 673503798).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Linda Boone

Signed: _____

Title: Agent _____

Date: 12/14/2016 2:07:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401166960	Seed Mix
401166967	Reclamation Site Photos

Total Attach: 2 Files