

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

682501478**FIELD INSPECTION FORM**
 Loc ID 311709 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 65550Name of Operator: OILFIELD SALVAGE & SERVICE COAddress: 5911 S MIDDLEFIELD RDCity: LITTLETON State: CO Zip: 80123**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		oilfieldsalvage@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200049	WELL	PA	08/17/1995	DSPW	001-05051	NOONEN RANCH 10	RI

General Comment:

This is a follow-up, final reclamation and stormwater inspection to inspection doc. #682501125. Please see inspection for more details.
Any corrective actions from previous inspections that have not been addressed are still applicable. Records show well PA 1995.

Inspected Facilities									
Facility ID:	200049	Type:	WELL	API Number:	001-05051	Status:	PA	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control **Fail** _____

Non cropland: Revegetated 80% **Fail** _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Inspection doc. 682501125 required Reclamation/Revegetation activities (including repairing a hole on location) were to be complete by 11/15/2016. No work appears to have been done at the time of this inspection. Original corrective actions and corrective action dates remain in place.

Corrective Action:

Date **11/16/2016**

Repair hole as required by corrective actions from inspection doc. #200089436, and inspection doc. #682501125. Stabilize the location, remediate soils (if needed) until soil meets COGCC 910-1 standards. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture that matches the adjacent pastureland or a seed mixture requested by the landowner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Remediation and revegetation activities shall be complete no later than 11/15/2016

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection doc. #682501125 required operator to install and maintain site specific stormwater and sediment control BMPs. BMPs have not been installed or maintained. Original corrective action and corrective action date of 9/9/2016 remains in place. See attached photo document.

Corrective Action: To prevent further degradation to the area properly select, install site specific stormwater and sediment control BMPs. BMPs shall be maintained throughout remediation until final reclamation passes.

Date: 09/09/2016

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Inspector had previous correspondence (phone and email) w/ Mr. Ross Unruh w/ Oilfield Salvage (OS). Mr. Unruh had stated in October that they (OS) and a crew were ready to begin work but were unable to find the location. Inspector was under the impression that this confusion had been cleared up through an email 11/22/2016. At time of inspection no work appears to have been conducted on the location. Emailed Mr. Ross Unruh at approximately 8:48 AM on 12/14/2016 to discuss the reclamation of the location. Mr. Unruh returned my message at 10:30 AM via phone. Mr. Unruh explained that he (Oilfield Salvage) will be meeting with the Surface Owner on December 16th 2016 to discuss the reclamation of the Noonan Ranch 10. This in combination with poor weather conditions, which hindered access to the location, and confusion finding the location are reasons as to why reclamation has been delayed.	trujilloam	12/14/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682501478	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033484
682501479	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027383