

FORM  
6Rev  
12/05State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

401152665

Date Received:

12/07/2016

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 44390

Contact Name: Kaulin Waldner

Name of Operator: JAVERNICK OIL

Phone: (303) 437-0082

Address: 3040 E MAIN

Fax:

City: CANON CITY State: CO Zip: 81212

Email: kaulin.waldner@dewpointwest.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

API Number 05-043-40002-00

Well Name: CHEROKEE &amp; PITTSBURG

Well Number: 535

Location: QtrQtr: NENW Section: 29 Township: 19S Range: 69W Meridian: 6

County: FREMONT

Federal, Indian or State Lease Number:

Field Name: FLORENCE-CANON CITY

Field Number: 24600

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 38.373670

Longitude: -105.135810

GPS Data:

Date of Measurement: 08/15/2006

PDOP Reading: 2.2

GPS Instrument Operator's Name: Larry Robbins

Reason for Abandonment:

☐ Dry☒ Production Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth: 3000

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
PIERRE					

Total: 1 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	8+1/4	6+5/8	17	185				
1ST	6	5	11.5	2,046				
1ST LINER	5	4+1/2	9.5	2,723				
2ND LINER	4	3+1/2	7	3,000				

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 248 with 10 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 20 sacks half in. half out surface casing from 194 ft. to 0 ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 685 ft. of 5 inch casing Plugging Date: 08/17/2016

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: Fremont Paving and Redi-Mix

Type of Cement and Additives Used: 23710# Sand Grout, 735# Cement, 188# Flyash, 417# wtr, yield 28.11cf

Flowline/Pipeline has been abandoned per Rule 1103 ☒ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

Entered CIBP#1 at 248' for wood plug set below surface casing in open hole w/ 10 sx sackrete on top. WOC till 8/23/16, tag plug. Set 20 sx sand grout at 193.7'-surface. Fremont Redi-Mix cement-sand slurry (23710# Sand Grout, 735# Cement, 188# Flyash, 417# wtr, yield 28.11cf.)

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Kaulin Waldner

Title: Authorized Agent Date: 12/7/2016 Email: kaulin.waldner@dewpointwest.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 1/12/2017

**CONDITIONS OF APPROVAL, IF ANY:**

**COA Type** **Description**

--	--

## Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401152665	FORM 6 SUBSEQUENT SUBMITTED
401162390	CEMENT JOB SUMMARY
401162391	WELLBORE DIAGRAM

Total Attach: 3 Files

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Agency	INSP: Began plugging 8/17/16. Finished plugging 9/6/16. Cut and capped 9/8/16. Recovered 685' of 5" casing.	01/12/2017

Total: 1 comment(s)