

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/10/2017
Submitted Date:
01/11/2017
Document Number:
680301568

FIELD INSPECTION FORM

Loc ID 313821 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 18600
Name of Operator: COLORADO INTERSTATE GAS COMPANY LLC
Address: P O BOX 1087
City: COLORADO State: CO Zip: 80944

Findings:
3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------------------|---------|
| Koehler, Bob | | bob.koehler@state.co.us | |
| Livley, Kevin | 970-867-4243 | kevin_lively@kindermorgan.com | |
| Lively, Kevin | 970-380-6011 | kevin_lively@kindermorgan.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|-----------------------|-------------|
| 150052 | UIC DISPOSAL | AC | 05/06/1963 | | - | FORT MORGAN UNIT 5 | AC |
| 225509 | WELL | IJ | 01/19/2012 | DSPW | 087-05922 | FORT MORGAN UNIT 5-WD | AC |

General Comment:
UIC/MIT Form 42 Doc# 401174341 received 12/28/2016
RESULT OF TEST - FAILED - Well lost pressure within first (5) min.
Note to Operator - Contact COGCC UIC Manager Bob Koehler for directives. Shut-in well and well must remain out of service until repaired and successful MIT has been performed.

Inspected Facilities

Facility ID: 150052 Type: UIC API Number: - Status: AC Insp. Status: AC

Facility ID: 225509 Type: WELL API Number: 087-05922 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: Failed MIT Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 01/17/2012
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: _____ Csg psi: 450 BH psi: _____

Insp. Status: Fail Leak Type: _____

Comment: Well loaded with fluid, pressurized to 450 psi., lost pressure within first (5) min. of test.

Corrective Action: Shut-in well. Well must remain out-of-service until repairs are performed and successful MIT has been witnessed. Contant Dr. Bob Koehler @ COGCC for directives. Corrective action date relates to requirement for shut-in well status. Corrective action date for MIT failure determined by COGCC Bob Koehler - please contact Mr. Koehler immediately upon receipt of this FIR. Date: 01/11/2017

COGCC Comments

| Comment | User | Date |
|---|-----------------|-------------------|
| <u>FAILED UIC/MIT - Contact COGCC UIC Manager - Dr. Robert Koehler for directives. Well must be shut-in and remain out-of-service until repairs are performed and successful MIT is witnessed by COGCC staff.</u> | <u>schureky</u> | <u>01/11/2017</u> |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|------------------|-----------------------------|--|
| <u>401182175</u> | <u>INSPECTION SUBMITTED</u> | <u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4048780</u> |