

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401203626  
Date Received:  
02/07/2017

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685301997  
Inspection Date: 12/20/2016 FIR Submit Date: 12/20/2016 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 333707

Location Name: LEMON GAS UNIT J-M34N8W Number: 17NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 17 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.188647 Longitude: -107.739895

### FACILITY - API Number: 05-067- -00 Facility ID: 258267

Facility Name: LEMON J Number: 2  
Qtrqtr: NWSE Sec: 17 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.188647 Longitude: -107.739895

### CORRECTIVE ACTIONS:

1 ☒ CA# 54664

Corrective Action: Install sign to comply with Rule 210.b Date: 02/19/2017

Response: CA COMPLETED Date of Completion: 02/01/2017

Operator Comment: New signs have been placed on location.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

Photo documentation provided by Operator shows corrective action completed.

2 ☒ CA# 54665

Corrective Action: Remove or install parts to comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 01/20/2017

Response: CA COMPLETED

Date of Completion: 01/25/2017

Operator  
Comment:

Corrective Action previously closed with FIRR form 401193265 see attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

Follow Up Inspection to be completed before 12/20/2017.

3 ☒ CA# 54666

Corrective Action: Repair or install required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 01/20/2017

Response: CA COMPLETED

Date of Completion: 01/25/2017

Operator  
Comment:

Corrective Action previously closed with FIRR form 401193265 see attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

Follow Up Inspection to be completed before 12/20/2017.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: New signs have been placed on location for all wells. Old signs require a truck with lift capabilities due to weight of base so these will be removed when the heavy duty truck with lift is available.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 2/7/2017 8:30:29 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401203626	FIR RESOLUTION SUBMITTED
401203644	FIRR document for previous closed DA
401203645	Sign CA documentation

Total Attach: 3 Files