

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2017

Submitted Date:

02/09/2017

Document Number:

674103929**FIELD INSPECTION FORM**
 Loc ID 440920 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440898	WELL	DG	05/04/2016	LO	123-41168	Jacobucci 32K-323	WK
440899	WELL	DG	04/18/2016	LO	123-41169	Jacobucci 32K-403	WK
440901	WELL	DG	04/11/2016	LO	123-41170	Jacobucci 32K-243	WK
441060	WELL	DG	03/31/2016	LO	123-41250	Jacobucci 32K-443	WK

General Comment:

Inspected Facilities

Facility ID: 440898 Type: WELL API Number: 123-41168 Status: DG Insp. Status: WK

Complaint

Comment: Complaint #:200441037

Field Inspector Assigned: Jeff Rickard

Location #: 440920

Inspection Document #: 674103929

Nature of complaint: Sound

If Sound GPS Coordinates of Survey Location: N/A

Inspection Observations:

OGCC inspector returned to location to try and run a sound survey. Current wind conditions were sustained winds out of the south of 8-10 mph, with gusts every 3 to 5 minutes of 14-16mph. Since wind conditions were above the 5mph limit for a valid sound survey, a survey was not run. Current weather forecast call for winds to increase as the day goes on. OGCC inspector will return tomorrow 2/10/17 to try and run a sound survey if wind conditions are appropriate.

Corrective Action:

Date:

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Other:

Observation:

Maximum Casing Recorded: PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back:

Fluid:

Gas:

Comment:

Corrective Action:

Date:

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 440899 Type: WELL API Number: 123-41169 Status: DG Insp. Status: WK

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Other:

Observation:

Maximum Casing Recorded: PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back:

Fluid:

Gas:

Comment:

Corrective Action:

Date:

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Facility ID: 440901 Type: WELL API Number: 123-41170 Status: DG Insp. Status: WK

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment:

Corrective Action:

Date: _____

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Facility ID: 441060 Type: WELL API Number: 123-41250 Status: DG Insp. Status: WK

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment:

Corrective Action:

Date: _____

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Complaint #:200441037 Field Inspector Assigned: Jeff Rickard Location #: 440920 Inspection Document #: 674103929 Nature of complaint: Sound If Sound GPS Coordinates of Survey Location: N/A Inspection Observations: OGCC inspector returned to location to try and run a sound survey. Current wind conditions were sustained winds out of the south of 8-10 mph, with gusts every 3 to 5 minutes of 14-16mph. Since wind conditions were above the 5mph limit for a valid sound survey, a survey was not run. Current weather forecast call for winds to increase as the day goes on. OGCC inspector will return tomorrow 2/10/17 to try and run a sound survey if wind conditions are appropriate.	rickardj	02/09/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401206106	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4071740