

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401220208

Date Received:

02/27/2017

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

- 1 CA Completed
- 1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26625
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
 Address: 12225 GREENVILLE AVE STE 950
 City: DALLAS State: TX Zip: 75243-9362

Contact Name and Telephone:
 Name: _____
 Phone: () _____ Fax: () _____
 Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lindeman, Terry</u>	<u>505-632-8048 EXT 210</u>	<u>tlindeman@elmridge.net</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Archuleta, Amy</u>	<u>505-632-3476 Ext 201</u>	<u>aarchuleta@elmridge.net</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901474
 Inspection Date: 02/17/2017 FIR Submit Date: 02/22/2017 FIR Status: _____

Inspected Operator Information:

Company Name: ELM RIDGE EXPLORATION COMPANY LLC Company Number: 26625
 Address: 12225 GREENVILLE AVE STE 950
 City: DALLAS State: TX Zip: 75243-9362

LOCATION - Location ID: 311901

Location Name: FASSETT GAS UNIT-N33N8W Number: 7SENW County: LA PLATA
 Qtrqtr: SENW Sec: 7 Twp: 33N Range: 8W Meridian: N
 Latitude: 37.121720 Longitude: -107.763260

FACILITY - API Number: 05-067-00 Facility ID: 216311

Facility Name: FASSETT GAS UNIT Number: 2
 Qtrqtr: SENW Sec: 7 Twp: 33N Range: 8W Meridian: N
 Latitude: 37.121720 Longitude: -107.763260

CORRECTIVE ACTIONS:

1 CA# 64900

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Date: 03/22/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

We would like to request an extension to rebuild the berm on location. We are requesting 30 days, bringing the due date to 4-21-17. The heavy precipitation and the amount of berms we plan to rebuild, we feel a 30 day extension is warranted.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 64901

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 03/22/2017

Response: CA COMPLETED

Date of Completion: 02/18/2017

Operator
Comment:

This action was complete before we received the field inspection form.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: _____

Title: Sr. Regulatory Supervisor

Date: 2/27/2017 3:50:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files