

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401220152

Date Received:

02/27/2017

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 26625  
Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
Address: 12225 GREENVILLE AVE STE 950  
City: DALLAS State: TX Zip: 75243-9362

Contact Name and Telephone:

Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Archuleta, Amy</u>		<u>aarchuleta@elmridge.net</u>
<u>Lindeman, Terry</u>	<u>505-632-8048 EXT 210</u>	<u>tlindeman@elmridge.net</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 674901481  
Inspection Date: 02/17/2017 FIR Submit Date: 02/22/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: ELM RIDGE EXPLORATION COMPANY LLC Company Number: 26625  
Address: 12225 GREENVILLE AVE STE 950  
City: DALLAS State: TX Zip: 75243-9362

### LOCATION - Location ID: 325165

Location Name: MILLER MESAVERDE UNIT-N33N8W Number: 6SWSE County: LA PLATA  
Qtrqtr: SWSE Sec: 6 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.128410 Longitude: -107.755680

### FACILITY - API Number: 05-067-00 Facility ID: 214181

Facility Name: MILLER MESAVERDE UNIT Number: 1  
Qtrqtr: SWSE Sec: 6 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.128410 Longitude: -107.755680

### CORRECTIVE ACTIONS:

1 ☒ CA# 64908

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 03/22/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment belongs to the surface owner

This steel beam is not owned by Elm Ridge Exploration. We believe this belongs to the land owner. It looks to be a structural piece of a building, not oilfield debris. If needed we can speak to land owner and ask that they remove

Operator Comment: it. It has been there since Elm Ridge purchased the well.

COGCC Decision: Approved

COGCC Representative: Steel beam is not on Location but adjacent to the Location.

COGCC Supervisor: Steel beam is not on Location but adjacent to the Location. No further action by the Operator is required regarding the steel beam.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed:

Title: Sr. Regulatory Supervisor

Date: 2/27/2017 3:31:07 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401220152	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files