

Post Spill Report

Date of Spill: 020717

Lease: NWAU #27 Well

Lease Operator: Kent Sramek

Comments/Concerns

Review Team:

Kent Sramek, Ray Brown, Tracy Akers, Clark Schreiber, Bill Stutz, Tom Engelbrecht, Trenton Akers, and Carl Smalley

Investigation Report/Basic Cause:

Stuffing box rubbers failed??????????????

Action Plan to Address the Root Cause:

Try to watch for repairs earlier

Production Foreman Tracy Akers

Date: 2-22-17

Tracy Akers