

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct intermediate casing test.
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 10112		11. Date of Test: 3-17-2017	
2. Name of Operator: Foundation Energy Management, LLC		12. Well Status: <input type="checkbox"/> Flowing <input checked="" type="checkbox"/> Shut In	
3. BLM Lease No:		<input type="checkbox"/> Gas Lift <input type="checkbox"/> Pumping <input type="checkbox"/> Injection	
4. API Number: 05-125-11735		<input type="checkbox"/> Clock/Intermittent	
5. Multiple completion? <input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Plunger Lift	
6. Well Name: Witte 21-36		13. Number of Casing Strings:	
7. Location (Qtr, Sec, Twp, Rng, Meridian): NE NW Sec 36 T15 R45W		<input checked="" type="checkbox"/> Two <input type="checkbox"/> Three <input type="checkbox"/> Liner?	
8. County: Yuma		9. Field Name: Vernon	
10. Minerals: <input type="checkbox"/> Fee <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> Indian			
14. STEP 1: EXISTING PRESSURES			
Record all pressures as found	Tubing: Fm:	Tubing: Fm:	Prod. Casing: Fm:
			Intermediate Csg: Fm:
			Surface Casing: Fm:

16. STEP 3: BRADENHEAD TEST					
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No					
With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas					
BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid					
Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black <input type="checkbox"/> Other: (describe) NA					
Sample cylinder number:					
Elapsed Time (Min:Sec)	Fm: Tubing:	Fm: Casing:	Production Casing PSIG	Intermediate Casing PSIG	Bradenhead Flow:
00:					O
05:					O
10:					O
15:					O
20:					O
25:					O
30:					O
Note instantaneous Bradenhead PSIG at end of test:					> O

17. STEP 4: INTERMEDIATE CASING TEST					
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No					
With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas					
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid					
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black <input type="checkbox"/> Other: (describe)					
Sample cylinder number:					
Elapsed Time (Min:Sec)	Fm: Tubing:	Fm: Casing:	Production Casing PSIG	Intermediate Casing PSIG	Intermediate Flow:
00:					
05:					
10:					
15:					
20:					
25:					
30:					
Note instantaneous Intermediate Casing PSIG at end of test:					>
18. Comments:					

19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed by: Kelly Sharp Title: Production Foreman Phone: 970-630-6880

Signed: *Kelly Sharp* Title: Production Foreman Date:

WITNESSED BY: *Susan Sh* Title: Field Inspection Agency: COGCC 3/17/17