

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2017

Submitted Date:

03/31/2017

Document Number:

669600027**FIELD INSPECTION FORM**Loc ID 334214 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258266	WELL	PR		GW	067-08346	LEMON H 2	PR
287905	WELL	PR	11/16/2006	GW	067-09268	LEMON H 3	PR
287906	WELL	PR	11/16/2006	GW	067-09267	LEMON H 4	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

**Inspected Facilities**Facility ID: 258266 Type: WELL API Number: 067-08346 Status: PR Insp. Status: PRFacility ID: 287905 Type: WELL API Number: 067-09268 Status: PR Insp. Status: PRFacility ID: 287906 Type: WELL API Number: 067-09267 Status: PR Insp. Status: PR

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Corrective actions completed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669600078	Berm and seeded area on fill slope.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113931">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113931</a>
669600079	Repaired erosion channel and seeded area.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113932">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113932</a>
669600080	Repaired erosion channel.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113933</a>
669600081	New berm above slope.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113934">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113934</a>