

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401249503  
Date Received:  
04/03/2017

FIR RESOLUTION FORM

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

0 CA Completed  
6 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071  
Name of Operator: BARRETT CORPORATION\* BILL  
Address: 1099 18TH ST STE 2300  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Binschus, Chris		chris.binschus@state.co.us
		COGCC_FIR@billbarrettcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682501786  
Inspection Date: 03/24/2017 FIR Submit Date: 03/28/2017 FIR Status:

Inspected Operator Information:

Company Name: BARRETT CORPORATION\* BILL Company Number: 10071  
Address: 1099 18TH ST STE 2300  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449306

Location Name: CVR Number: 5-63-32\_33 NWSW County:  
Qtrqr: NWS Sec: 32 Twp: 5N Range: 63W Meridian: 6  
Latitude: 40.352747 Longitude: -104.468622

FACILITY - API Number: 05-123-00 Facility ID: 449306

Facility Name: CVR Number: 5-63-32\_33 NWSW  
Qtrqr: NWS Sec: 32 Twp: 5N Range: 63W Meridian: 6  
Latitude: 40.352747 Longitude: -104.468622

CORRECTIVE ACTIONS:

1 CA# 69341

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f. Date: 04/04/2017  
Response: FACTUAL REVIEW REQUEST  
Basis for Review: Corrective action dates are not attainable

BBC is asking for an extension as work was going to be completed 4/3 but after multiple rain/snow events since

Operator Comment: the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor: FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

2 CA# 69342

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f. Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor: FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

3 CA# 69343

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f. Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor: FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

4 CA# 69344

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f. Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

5 CA# 69345

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment:

BBC is asking for an extension as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

6 CA# 69346

Corrective Action: Install BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment:

BBC is asking for an extension as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

[Empty comment box]

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracey Fallang

Signed:

Title: Regulatory Manager

Date: 4/3/2017 12:56:08 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401249503	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files