

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

669600039**FIELD INSPECTION FORM**Loc ID 326245 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216099	WELL	PR	05/03/2005	GW	067-07705	BLACK 21-22 1	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

Inspected Facilities									
Facility ID:	216099	Type:	WELL	API Number:	067-07705	Status:	PR	Insp. Status:	PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Spill prevention under lube oil tank.
Waddles	Pass					
Check Dams	Pass	Gravel	Pass			
Gravel	Pass					
Rip Rap	Pass					

Comment: [Corrective action completed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248916	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114280</a>
669600149	Erosion channel repair and reseeded area.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114264</a>
669600150	Erosion channel repair.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114265">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114265</a>
669600152	Spill prevention under lube oil tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114266">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114266</a>