

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2017

Submitted Date:

04/10/2017

Document Number:

680301849**FIELD INSPECTION FORM**Loc ID 312296 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Contact, General		regulatory@foundationenergy.com	All inspections
Axelson, John		john.axelson@state.co.us	
Eisterhold, Racheal		regulatory@foundationenergy.com	N.E. Colo. inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221124	WELL	PR	07/09/1997	OW	075-09250	BANEY-STATE 16-2	PR

General Comment:

Follow-up inspection FIR. Citations referenced in Doc# 680301811 related to removal of unused equipment (pump jack) and effected soils @ pump jack have been resolved. All other compliance directives from COGCC Environmental Group remain in effect until released by COGCC Environmental Group. This FIR is addressing only the surface equipment removal and soil removal and remediation cited with CA date of 03/31/2017.

Baney State 16-3 & Baney State 16-5 including related facility have returned to service/production. Compliance with COGCC Environmental Group directives are not identified within this FIR pending review by COGCC Environmental Group.

Location**Lease Road:**

Type	Access		
comment:	Access from Logan Count Road 34.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Replace signage at wellhead as soon as possible.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Pump Jack and saturated soils have been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221124 Type: WELL API Number: 075-09250 Status: PR Insp. Status: PR**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Pump jack and equipment at wellhead have been removed as cited in Doc# 680301811 FIR.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	268617	1241399	
	268617	1241399	

COGCC Comments

Comment	User	Date
FIR performed to confirm compliance for removal of unused equipment and saturated soils @ wellhead. Removal/remediation of pump jack and effected soils @ wellhead, has been performed. All remaining compliance issues from Doc# 680301811 remain unresolved until released by COGCC Environmental Group. (2) remaining wells related to this facility have been returned to service/production.	schureky	04/10/2017