

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401263292

Date Received:

04/20/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Randy Jakel

9703817155

riakel@verdadoil.com

Arthur Beecherl

2147281840

abeecherl@verdadoil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685502456

Inspection Date: 04/13/2017

FIR Submit Date: 04/13/2017

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

LOCATION - Location ID: 445809

Location Name: State Number: 02-63-16-1H County: WELD

Qtrqtr: SESE Sec: 16 Twp: 2N Range: 63W Meridian: 6

Latitude: 40.131965 Longitude: -104.433684

FACILITY - API Number: 05-123- -00 Facility ID: 445808

Facility Name: State Number: 02-63-16-1H

Qtrqtr: SESE Sec: 16 Twp: 2N Range: 63W Meridian: 6

Latitude: 40.131965 Longitude: -104.433684

CORRECTIVE ACTIONS:

1 CA# 70957

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 04/28/2017

Response: CA COMPLETED

Date of Completion: 04/19/2017

Operator Comment: This location is not in an exception zone as permitted. All berms and secondary containment are in place.

COGCC Decision: _____

COGCC
Representative:

2 CA# 70958

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 04/28/2017

Response: CA COMPLETED

Date of Completion: 04/19/2017

Operator
Comment: This location is not in an exception zone as permitted. Fresh H2O is seeping to surface due to lined containment and is reason for watermarks. There is no evidence of a spill inside lined berm.

COGCC Decision: _____

COGCC
Representative:

3 CA# 70959

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 05/13/2017

Response: CA COMPLETED

Date of Completion: 04/19/2017

Operator
Comment: Stained pea gravel removed and disposed.

COGCC Decision: _____

COGCC
Representative:

4 CA# 70960

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 05/13/2017

Response: CA COMPLETED

Date of Completion: 04/19/2017

Operator
Comment: Berm holes were as pictured are 3" deep footprints and not leak exposure points. Smoothed out.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: L. ARthur Beecherl, IV

Signed: _____

Title: VP of Operations

Date: 4/20/2017 7:45:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files