



Photo 1: Empire Electric removed their pipe from location.



Photo 2: Control measures installed to prevent future erosion.



Photo 3: Windblown trash has been removed from fence line.