



photo 1: Facing northwest toward the location.



photo 2: Area around dry hole marker does not have adequate vegetation establishment.



photo 3: Well marker plate.



photo 4: Facing east toward the location.