

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2017

Submitted Date:

05/12/2017

Document Number:

677900233**FIELD INSPECTION FORM**
 Loc ID 391537 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 87815Name of Operator: THINK OIL INCAddress: 11094 FITZHUGH RDCity: AUSTIN State: TX Zip: 78736**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

**General Comment:**

On May 10, 2017 COGCC Environmental Staff (Alex Fischer and Kris Neidel) conducted an environmental field inspection of Think Oil Inc Vaughn #1 Location ID: 391537, API 081-05332.. Weather was overcast and light rain and temperature app 50s degree F. The well has been P and A. was not producing at time of inspection. For the most recent Field inspection report of this facility, please refer to document # 670201404.

The following is a summary:

- There are two spoil piles (approximately 8'x 6' x 4') of alleged E&P impacted waste.
- There is an approximate 48-inch by 24-inch container of oil soaked absorbent pads and E&P impacted soil.
- An approximate 20' long by 4' wide by 2' deep depression where fresh water as allegedly disposed of.
- Open excavation (10-diameter by 4 feet in depth) around the P&Aed Vaughn #1, API 081-05332 well.

Corrective Actions:

Remove and properly dispose of the two spoil piles, container of oily material, impacted material around the well head, and surficial soil in the depression.

Finalize the abandonment of the Vaughn #1 well.

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	<ul style="list-style-type: none"> <li>• There are two spoil piles (approximately 8'x 6' x 4') of alleged E&amp;P impacted waste.</li> <li>• There is an approximate 48-inch by 24-inch container of oil soaked absorbent pads and E&amp;P impacted soil.</li> <li>• Open excavation (10-diameter by 4 feet in depth) around the P&amp;Aed Vaughn #1, API 081-05332 well.</li> </ul>			
Corrective Action	<p>Remove and properly dispose of the two spoil piles, container of oily material, impacted material around the well head, and surficial soil in the depression.</p> <p>Finalize the abandonment of the Vaughn #1 well.</p>			Date: _____

**Spill/Remediation:**

Comment:	• An approximate 20' long by 4' wide by 2' deep depression where fresh water as allegedly disposed of.		
Corrective Action:	Remove surficial soil and properly dispose.		
			Date: _____

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>On May 10, 2017 COGCC Environmental Staff (Alex Fischer and Kris Neidel) conducted an environmental field inspection of Think Oil Inc Vaughn #1 Location ID: 391537, API 081-05332.. Weather was overcast and light rain and temperature app 50s degree F. The well has been P and A. was not producing at time of inspection. For the most recent Field inspection report of this facility, please refer to document # 670201404.</p> <p>The following is a summary:</p> <ul style="list-style-type: none"> <li>• There are two spoil piles (approximately 8'x 6' x 4') of alleged E&amp;P impacted waste.</li> <li>• There is an approximate 48-inch by 24-inch container of oil soaked absorbent pads and E&amp;P impacted soil.</li> <li>• An approximate 20' long by 4' wide by 2' deep depression where fresh water as allegedly disposed of.</li> <li>• Open excavation (10-diameter by 4 feet in depth) around the P&amp;Aed Vaughn #1, API 081-05332 well.</li> </ul> <p>Corrective Actions:</p> <p>Remove and properly dispose of the two spoil piles, container of oily material, impacted material around the well head, and surficial soil in the depression.</p> <p>Finalize the abandonment of the Vaughn #1 well.</p>	fischera	05/12/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677900234	20170510 Think Oil Location ID 391537 API 08105332.pdf	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146245">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146245</a>
677900235	20170510 Photolog Think Oil Location ID 391537 API 08105332.pdf	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146246">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146246</a>