

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401215343
Date Received:
02/21/2017

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Luke Reddy 970-515-1292 luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674004796
Inspection Date: 01/20/2017 FIR Submit Date: 01/20/2017 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 317939

Location Name: HELEN MARIE PURSE UNIT Number: 2SENE County: WELD
B-63N67W
Qtrqtr: SENE Sec: 2 Twp: 3N Range: 67W Meridian: 6
Latitude: 40.256964 Longitude: -104.853308

FACILITY - API Number: 05-123-00 Facility ID: 240213

Facility Name: HELEN MARIE PURSE Number: B1
Qtrqtr: SENE Sec: 2 Twp: 3N Range: 67W Meridian: 6
Latitude: 40.256964 Longitude: -104.853308

CORRECTIVE ACTIIONS:

1 CA# 63068

Corrective Action: Install berm appropriate for flood plain.

Date: 02/20/2017

NOTE: THIS IS NOT EFFECTIVE UNTIL APRIL 1, 2016 FOR EXISTING WELLS --
Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details. The tanks do not appear to be constructed following an engineered design plan.

Response: CA COMPLETED

Date of Completion: 02/20/2017

Operator Comment: Earthen berms are being replaced with steel berms

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 63069

Corrective Action: NOTE: THIS IS NOT EFFECTIVE UNTIL APRIL 1, 2016 FOR EXISTING WELLS -- Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.
Tank does not appear to be constructed following an engineered design plan.

Date: 02/20/2017

Response: CA COMPLETED Date of Completion: 02/20/2017

Operator Comment: equipment is being adequately anchored

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Earthen berms are being replaced with steel berms
equipment is being adequately anchored

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy Signed: _____
Title: Regulatory Specialist Date: 2/21/2017 2:02:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401215343	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files