

Inspection Photos
Location Name: Sand Hills Federal 43-20
API: 05-081-06960



Photo 1. Overview of location taken at the entrance facing northeast.



Photo 2. Plugging debris on location.

Inspection Photos
Location Name: Sand Hills Federal 43-20
API: 05-081-06960



Photo 3. Unmarked 2" steel riser at 40.97718, -107.62582.



Photo 4. Unmarked 3" steel riser at 40.97712, -107.62637.