

Lopez Salt Water Disposal Well API# 05-071-09733

Date: June 08, 2017

COGCC FIR Document # 673504275 (2) Corrective Actions are complete.



Photo 1: Facing toward the access road of location.



Photo 2: Facing southwest toward the location



Photo 3: Facing southwest corner of the well pad cut slope. The sediment was removed from the pad.



Photo 4: Established a bell hole at the toe of the rock run down to retain sediment. Installed a dirt berm on the terraced cut slope to direct run off away from the cut slope.




Photo 5: Installed a dirt berm on the terraced cut slope to direct run off away from the cut slope of the well pad.



Photo 6: Run off was re-directed to flow down the terrace toward a culvert with an armored outlet.




Photo 7: Run off from the terrace flows north to a culvert inlet. This will reduce the flow on the well pad cut slope.



Photo 8: Culvert outlet is armored to prevent erosion from run off.

Lopez Salt Water Disposal Well API# 05-071-09733

Date: June 08, 2017

COGCC FIR Document # 673504275 (2) Corrective Actions are complete.



Photo 9: Southeast side of the location facing west. The red arrow points to where noxious weeds were treated on 05/18/17.



Photo 10: The Canada thistle and Common mullein that were growing in the rock rip rap on the south side of location were treated on 05/18/17.