

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401306395
Date Received:
06/12/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: BARRETT CORPORATION* BILL
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Matt Barber</u>	<u>303-312-8188</u>	<u>mbarber@billbarrettcorp.com</u>
<u>Matt Schwartz</u>	<u>303-312-8142</u>	<u>maschwartz@billbarrettcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682501981
Inspection Date: 05/11/2017 FIR Submit Date: 05/12/2017 FIR Status: _____

Inspected Operator Information:

Company Name: BARRETT CORPORATION* BILL Company Number: 10071
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449383

Location Name: Hawkins Number: 5-61-20_19 County: _____
SW21
Qtrqtr: NWS Sec: 21 Twp: 5N Range: 61W Meridian: 6
W
Latitude: 40.385989 Longitude: -104.222578

FACILITY - API Number: 05-123- -00 Facility ID: 449383

Facility Name: Hawkins Number: 5-61-20_19
SW21
Qtrqtr: NWS Sec: 21 Twp: 5N Range: 61W Meridian: 6
W
Latitude: 40.385989 Longitude: -104.222578

CORRECTIVE ACTIONS:

1 CA# 75526

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 06/12/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

BMP repaired as per Rule 1002.f with good engineering practices - sediment traps being enlarged, small eroded

Operator Comment: areas cleaned up and outlet protection installed. Ditch improvements.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 75527

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 06/12/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - sediment traps being enlarged, small eroded areas cleaned up and outlet protection installed. Ditch improvements.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 75528

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 05/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - sediment traps being enlarged, small eroded areas cleaned up and outlet protection installed. Ditch improvements.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed: _____

Title: Sr. Permit Analyst

Date: 6/12/2017 3:47:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

Total Attach: 0 Files