

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401306440
Date Received:
06/12/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: BARRETT CORPORATION* BILL
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Matt Barber</u>	<u>303-312-8188</u>	<u>mbarber@billbarrettcorp.com</u>
<u>Matthew Schwartz</u>	<u>303-312-8142</u>	<u>maschwartz@billbarrettcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682501979
Inspection Date: 05/11/2017 FIR Submit Date: 05/12/2017 FIR Status: _____

Inspected Operator Information:

Company Name: BARRETT CORPORATION* BILL Company Number: 10071
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449306

Location Name: CVR Number: 5-63-32_33 County: _____
NWSW
Qtrqtr: NWS Sec: 32 Twp: 5N Range: 63W Meridian: 6
W
Latitude: 40.352747 Longitude: -104.468622

FACILITY - API Number: 05-123- -00 Facility ID: 449306

Facility Name: CVR Number: 5-63-32_33
NWSW
Qtrqtr: NWS Sec: 32 Twp: 5N Range: 63W Meridian: 6
W
Latitude: 40.352747 Longitude: -104.468622

CORRECTIVE ACTIONS:

1 CA# 75522

Corrective Action: Comply with rule 603.f Date: 05/22/2017
Response: CA COMPLETED Date of Completion: 06/05/2017
Fulfilled with rule 603.f - stormwater ditch was cleaned out.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 75523

Corrective Action: Corrective action has not been addressed and remains applicable. Original CA and extended date remains in place: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - ditch was cleaned out, sediment traps cleaned up and outlet protection installed.

COGCC Decision:

COGCC
Representative:

3 CA# 75524

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - ditch was cleaned out, sediment traps cleaned up and outlet protection installed.

COGCC Decision:

COGCC
Representative:

4 CA# 75525

Corrective Action: Corrective action has not been addressed and remains applicable. Original CA and extended date remains in place: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - ditch was cleaned out, sediment traps cleaned up and outlet protection installed.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

