

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401306440  
Date Received:  
06/12/2017

## FIR RESOLUTION FORM

### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10071  
Name of Operator: BARRETT CORPORATION\* BILL  
Address: 1099 18TH ST STE 2300  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Matt Barber</u>	<u>303-312-8188</u>	<u>mbarber@billbarrettcorp.com</u>
<u>Matthew Schwartz</u>	<u>303-312-8142</u>	<u>maschwartz@billbarrettcorp.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682501979  
Inspection Date: 05/11/2017 FIR Submit Date: 05/12/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BARRETT CORPORATION\* BILL Company Number: 10071  
Address: 1099 18TH ST STE 2300  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 449306

Location Name: CVR Number: 5-63-32\_33 County: \_\_\_\_\_  
NWSW  
Qtrqtr: NWS Sec: 32 Twp: 5N Range: 63W Meridian: 6  
W  
Latitude: 40.352747 Longitude: -104.468622

### FACILITY - API Number: 05-123- -00 Facility ID: 449306

Facility Name: CVR Number: 5-63-32\_33  
NWSW  
Qtrqtr: NWS Sec: 32 Twp: 5N Range: 63W Meridian: 6  
W  
Latitude: 40.352747 Longitude: -104.468622

### CORRECTIVE ACTIONS:

1 ☒ CA# 75522

Corrective Action: Comply with rule 603.f Date: 05/22/2017  
Response: CA COMPLETED Date of Completion: 06/05/2017

Fulfilled with rule 603.f - stormwater ditch was cleaned out.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

2 ☒ CA# 75523

Corrective Action: Corrective action has not been addressed and remains applicable. Original CA and extended date remains in place: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - ditch was cleaned out, sediment traps cleaned up and outlet protection installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

3 ☒ CA# 75524

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - ditch was cleaned out, sediment traps cleaned up and outlet protection installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

4 ☒ CA# 75525

Corrective Action: Corrective action has not been addressed and remains applicable. Original CA and extended date remains in place: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/11/2017

Response: CA COMPLETED

Date of Completion: 06/05/2017

Operator Comment: BMP repaired as per Rule 1002.f with good engineering practices - ditch was cleaned out, sediment traps cleaned up and outlet protection installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed: \_\_\_\_\_

Title: Sr. Permit Analyst

Date: 6/12/2017 3:54:09 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401306440	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files