

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2017

Submitted Date:

06/15/2017

Document Number:

687900003

FIELD INSPECTION FORM

Loc ID 322222 Inspector Name: DURAN, JOHN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16245
 Name of Operator: CHARLES ANTHONY FUNERAL HOME
 Address: 225 E MAIN
 City: FLORENCE State: CO Zip: 81226

Findings:

- 6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Malin, Carol	719-458-1552	carol.harwoodfuneral@gmail.com	All Inspections
Harwood, Lloyd	719-458-1552/ 719-334-2445	harwoodfuneral@yahoo.com	Canyon City Office
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210030	WELL	DM	05/12/1996	GW	043-06108	PRIDE OF WEST 1	DM

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	and separator fenced by guard rail.		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Ancillary equipment	# 1				
Comment:	Wellhead				
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210030 Type: WELL API Number: 043-06108 Status: DM Insp. Status: DM

Producing Well

Comment: [PR - Domestic producer that heats funeral parlor and heats retort oven in crematorium.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Paving	Pass	Paving	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
I arrived in Florence at 2:30 pm. I met with Lloyd Harwood and I told him, his newly acquired gas well was in violation of Rule 302.a., 302.b., 312.i., 706 and 708. I told him he needed to put up a bond on the well and get registered as a owner/operator with the COGCC. He agreed that they would not cremate any more bodies, until they had completed all the paper work and put up financial security for the well. I did leak checks with soapy water on 1 inch line and fittings from well to funeral parlor. The 3 inch line from well to crematorium is 8 ft off the ground. I will return with ladder. Off site at 5:30 pm.	duranj	06/15/2017