

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2017

Submitted Date:

06/16/2017

Document Number:

680601667

**FIELD INSPECTION FORM**

Loc ID 326272 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**

6 Number of Comments  
2 Number of Corrective Actions

Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		Sabre.Beebe@bp.com	<a href="#">All Inspections</a>
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216147	WELL	PR	01/04/1992	GW	067-07753	RICHARDSON E 1	RI

**General Comment:**

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)  
[Corrective action dates are based off of the date the inspection is submitted, not the actual inspection date.](#)

**Inspected Facilities**

Facility ID: 216147 Type: WELL API Number: 067-07753 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by ponderosa pine woodland. Revegetation on cut-slope is sparse and progressing on northern and southern fill slopes.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_



<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <span style="color: blue;">Stormwater erosion is occurring in the eastern portion of the project area where concentrated stormwater flows down and erodes the fill slopes.</span>						
Corrective Action: <span style="color: red;">Stormwater controls need to be installed to stabilize erosion within the project area.</span>						Date: 07/17/2017
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601668	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172970">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172970</a>