

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401316557
Date Received:
06/22/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26580

Name of Operator: BURLINGTON RESOURCES OIL & GAS LP

Address: PO BOX 4289

City: FARMINGTON State: NM Zip: 87499

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dixon, Jennifer

Jennifer.A.Dixon@conocophillips.com

Williams, Donna

donna.j.williams@conocophillips.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402119

Inspection Date: 05/16/2017

FIR Submit Date: 05/19/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BURLINGTON RESOURCES OIL & GAS LP

Company Number: 26580

Address: PO BOX 4289

City: FARMINGTON State: NM Zip: 87499

LOCATION - Location ID: 428476

Location Name: BOMHOFF Number: 5-8H County: ARAPAHOE

Qtrqr: SWN Sec: 9 Twp: 4S Range: 64W Meridian: 6
W

Latitude: 39.719119 Longitude: -104.563678

FACILITY - API Number: 05-005- -00 Facility ID: 428474

Facility Name: BOMHOFF Number: 5-8H

Qtrqr: SWN Sec: 9 Twp: 4S Range: 64W Meridian: 6
W

Latitude: 39.719119 Longitude: -104.563678

CORRECTIVE ACTIONS:

1 CA# 76901

Corrective Action: The Operator shall use best available BMPs to control noxious weeds and to prevent further spreading onto adjacent lands.

Date: 06/16/2017

Response: CA COMPLETED

Date of Completion: 06/21/2017

Operator Comment: Work was delayed due to the recent storms in the area and wet ground conditions. Work was started the week of 6/12/17 week and completed 6/21/17.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 76902

Corrective Action: Perform interim reclamation on all areas not reasonably needed for production operations in accordance to reclamation rules.

Date: 11/15/2017

Response: CA COMPLETED

Date of Completion: 11/15/2017

Operator Comment: Pad size has not been reduced. Operator will perform interim reclamation on all areas not reasonably needed for production operations or for subsequent drilling operations per Rule 1003.b. as described in interim reclamation plan.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 76903

Corrective Action: Install or repair required BMPs per rule 1002.f.

Date: 06/16/2017

Response: CA COMPLETED

Date of Completion: 06/21/2017

Operator Comment: Work was delayed due to the recent storms in the area and wet ground conditions. Work was started the week of 6/12/17 week and completed 6/21/17.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Work was delayed due to the recent storms in the area and wet ground conditions. Work was started the week of 6/12/17 and completed 6/21/17.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jennifer Dixon

Signed: _____

Title: Regulatory Coordinator

Date: 6/22/2017 4:32:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401316618	BMP Repair Photo
-----------	------------------

Total Attach: 1 Files