

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2017

Submitted Date:

06/19/2017

Document Number:

680200071**FIELD INSPECTION FORM**

Loc ID 440634 Inspector Name: KELLERBY, SHAUN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ash, Margaret		margaret.ash@state.co.us	
Lind, Jennifer	(720) 508-8362	jlind@ursaresources.com	All Inspections
Murray, Richard		g.richard.murray@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440637	WELL	DG	02/22/2017	LO	045-22709	B&V 41A-13-07-96	WK
441598	WELL	WO	02/22/2017	LO	045-22845	B&V 11B-18-07-95	WK

General Comment:[Inspection is in response to a noise complaint Doc # 200442778.](#)

Inspected FacilitiesFacility ID: 440637 Type: WELL API Number: 045-22709 Status: DG Insp. Status: WK**Complaint**

Comment: Operator has submitted Form 42 notice of Hydraulic Fracturing Doc # 401300563 on 6/5/17 with a start date of 6/9/17. Sound measurement was conducted during Stimulation operations on 6/16/17.

Sound Measurement indicated a dbc level above 65 dbc .

Corrective Action: Submit a sound mitigation plan to bring dbc sound measurement levels into compliance with Cogcc rules.

Date: 06/21/2017

Facility ID: 441598 Type: WELL API Number: 045-22845 Status: WO Insp. Status: WK**Complaint**

Comment: Operator has submitted Form 42 notice of Hydraulic Fracturing Doc # 401300565 on 6/5/17 with a start date of 6/9/17. Sound measurement was conducted during Stimulation operations on 6/16/17.

Sound Measurement indicated a dbc level above 65 dbc .

Corrective Action: Submit a sound mitigation plan to bring dbc sound measurement levels into compliance with Cogcc rules.

Date: 06/21/2017

COGCC Comments

Comment	User	Date
FIRR was submitted on 6/9/2017 Doc # 401305037. Corrective actions required on FIR Doc # 680200068 were reported to be complete and ready for inspection. A sound measurement was conducted on 6/16/17. dbc level remain above 65.	kellerbs	06/19/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311731	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173912
680200072	Sound Measurment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173911