

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: Followup inspection to assess release observed by Kyle Granahan on 5/10/17 during COGCC Insp # 675103583. Small skid-mounted pumpjack has pooled crude oil around wellhead. Visible leakage around stuffing box. Soil is stained black with strong petroleum odor.

Corrective Action: Crude oil has been released in an amount greater than one barrel. Operator must submit a Form 19 spill report within 24 hours of receipt of this inspection. Repair pumpjack as necessary to prevent any further release of oil to the environment. Assess nature and extent of contamination with confirmation soil samples. Remediate soil and/or groundwater to COGCC Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation of contaminated soil is required. Documentation must include a figure showing spill area with sample locations plus laboratory results. Supplemental F-19 must be submitted within 10 days. Remediation must be in progress within 30 days.

Date: 07/26/2017

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401319610	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181103
674300914	Leaking wellhead looking SW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181101
674300915	Leaking wellhead looking S	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181102