

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2017

Submitted Date:

07/25/2017

Document Number:

679700562**FIELD INSPECTION FORM**

Loc ID 433684 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Field		COGCC_FIR@billbarrettcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451487	SPILL OR RELEASE	AC			-	Hawkins 5-61-21 water transfer pump	EI

General Comment:

COGOCC Environment Staff inspection of reported produced water spill at transfer pump in water storage facility.

Environmental**Spill/Remediation:**

Comment: Operator reported spill discovered on 7/23/2017. Produced water spill occurred within lined containment. Containment was breached on north end. No standing liquid was observed on the location. See attached pictures. Operator is to continue with spill cleanup, investigation of liner breach and potential impact to soil, root cause analysis for pump failure and reporting per rule 906.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401354028	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207733
679700567	Spill impacts within secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207722
679700568	Spill impacts to pad surface north of containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207723
679700569	Containment breach on north end of facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207724
679700570	Impacts within containment near shed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207725