

August 4, 2017

Jonte Rosebrough  
1373 Washburn St.  
Erie, CO 80516  
via email: jonte1177@me.com

Dear Mr. Rosebrough,

The Colorado Oil and Gas Conservation Commission (COGCC) received your complaint(s) regarding noise from an oil and gas operation in the vicinity of your residence on 12:00:00 AM. Your complaint is documented in the COGCC database as COGCC document number 0, which can be found via the "Complaints" link, on our website (<http://cogcc.state.co.us/>).

COGCC staff completed the following actions to investigate your complaint:

- On 05/18/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location, operated by Crestone Peak Resources Operating LLC (documented in Field Inspection Report [FIR] # 674200073);
- The inspection included the location where remote hydraulic fracturing operations are being conducted;
- The inspector reviewed location records which did not show any abnormal conditions;
- The inspector reviewed Environmental Noise Control Inc. continuous sound study data. The data indicated that the location was in compliance with the maximum permissible noise levels established in COGCC Rule 802;
- The inspector did not conduct additional sound studies, because weather conditions precluded sound measurements;
- On 05/24/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 674200088) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802;
- On 05/26/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 674200099) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802;
- During the inspection, the inspector conducted a sound study approximately 40 feet from the closest residence in the direction of the location. The survey determined that the average sound levels were 52.6 decibels (dB) on the A-scale and 65 decibels on the C-scale, which is in compliance with the maximum permissible noise levels established in COGCC Rule 802;
- On 05/30/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 674200112) where location records did not show any



abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802;

- Additionally, the inspector noted all lighting was directed downward and inward in compliance with COGCC Rule 803 and that no abnormal odors were detected;
- On 06/12/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 674200116) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802;
- Additionally, the inspector noted all lighting was directed downward and inward in compliance with COGCC Rule 803 and that no abnormal odors were detected;
- On 06/19/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 674200121) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802;
- On 06/29/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 674200135) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802;
- Additionally, the inspector noted all lighting was directed downward and inward in compliance with COGCC Rule 803 and that no abnormal odors were detected;
- On 07/05/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 681902233) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802; and
- On 07/20/2017 a COGCC Field Inspector conducted an inspection of the Woolley Sosa location (documented in FIR # 688400012) where location records did not show any abnormal conditions and Noise Control Inc. continuous sound study data demonstrated compliance with COGCC Rule 802.

COGCC FIRs, including location photos and sound study documentation, are available on the COGCC website by selecting "Inspection/ Incident" under the data search link.

No instances of non-compliance, with COGCC rules, were observed during the investigation into this noise complaint. Based on the above described investigation, the COGCC has determined that no violations of COGCC rules occurred related to your complaint. Accordingly, the COGCC has closed the complaint and will not issue a notice of alleged violation (NOAV) related to this complaint.

If you have questions regarding this complaint or the investigation, please contact me.

Sincerely,



Megan Adamczyk, Complaint Specialist  
Phone: 888-235-1101  
Email: [dnr\\_cogcc.complaints@state.co.us](mailto:dnr_cogcc.complaints@state.co.us)