

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2017

Submitted Date:

07/28/2017

Document Number:

690100030

FIELD INSPECTION FORM

Loc ID 320332 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
Witsell, Fred	303-500-1168	fwitsell@petrosharecorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203466	WELL	PR	11/01/2014	GW	001-09025	SELTZER G U 2-4	TA

General Comment:

[Audible gas leak identified at wellhead; See venting section of this report. Photo's attached.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	Audible gas leak identified at wellhead during field inspection.		
Corrective Action:	Make equipment repairs and stop gas leak at wellhead; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.	Date:	08/01/2017

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203466 Type: WELL API Number: 001-09025 Status: PR Insp. Status: TA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: This well is Temporarily Abandoned; The flowline has been disconnected and abandoned; flowline cut off below grade at wellhead and horizontal separator. This well is not capable of producing.

Corrective Action: Schedule and Perform Mechanical Integrity Test; 10 day notice required. Contact COGCC Engineering Department.

Date: 08/28/2017

326 c. Temporarily Abandoned Wells – All temporarily abandoned wells shall pass a mechanical integrity test.
(1) A mechanical integrity test shall be performed on each temporarily abandoned well within 30 days of temporarily abandoning the well.

COGCC Comments

Comment	User	Date
There is no form 6 (Intent to Abandon) located in the COGCC well file.	maclarej	07/28/2017
COGCC Inspector called Petroshare Field Operations Manager Harold Powell and left a voicemail (Cell) regarding the audible wellhead gas leak on 7/28/17 @ 10:30 am; Voicemail also left at office on 7/28/17 @ 12:00pm.	maclarej	07/28/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401357906	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210077
690100031	Wellhead and Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210070
690100032	Wellhead with flowline disconnected/ removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210071
690100033	Flowline(s) disconnected/ removed ata separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210072
690100034	Area of audible gas leak at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210073