

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2017

Submitted Date:

08/09/2017

Document Number:

682402572**FIELD INSPECTION FORM**Loc ID: 305317 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
		phillip.porter@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451077	WELL	XX	06/14/2017		123-44970	High Plains 25F-301	CI
451078	WELL	XX	06/14/2017		123-44971	High Plains 25A-401	CI
451079	WELL	XX	06/14/2017		123-44972	High Plains 25N-301	CI
451080	WELL	XX	06/14/2017		123-44973	High Plains 25N-241	CI
451081	WELL	XX	06/14/2017		123-44974	High Plains 25A-241	CI
451082	WELL	XX	06/14/2017		123-44975	High Plains 25A-221	CI
451083	WELL	XX	06/14/2017		123-44976	High Plains 25A-341	CI
451084	WELL	XX	06/14/2017		123-44977	High Plains 25F-221	CI
451085	WELL	XX	06/14/2017		123-44978	High Plains 25A-321	CI

General Comment:

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401355800.

Location ConstructionLocation ID: 305317 CDP: _____Comment: Topsoil stockpile has been stored and temporarily stabilized along the southern and eastern perimeter of the location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____

Date: _____

Form 2A COAs:Comment: A disturbance area of 9.50 acres was mapped on 8/8/2017 using a Trimble Juno 3B handheld device.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action:

Date:

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS	Yes	Vehicle Trakcing	Yes`

Comments: Erosion BMPs: Berm installed around the perimeter of the location.

Other BMPs:

Corrective Action:

Date:

RETENTION PONDS

Yes

Comments: Erosion BMPs: Operator appears to be installing sediment traps but with no stabilized outlet. Embankment berms do not appear to be properly compacted. Operator shall complete the sediment trap installation so the location has proper outlet protection to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Other BMPs:

Corrective Action:

Date:

DITCHES

Yes

Comments: Erosion BMPs: Ditch installed around the perimeter of the location.

Other BMPs:

Corrective Action:

Date:

Comment:Corrective Action:

Date:

On Site Inspection (305):Surface Owner Contact Information:

Name:

Address:

Phone Number:

Cell Phone:

Operator Rep. Contact Information:

Landman Name:

Phone Number:

Date Onsite Request Received:

Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name:

Phone Number:

Agreed to Attend:

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>451077</u>	Type: <u>WELL</u>	API Number: <u>123-44970</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451078</u>	Type: <u>WELL</u>	API Number: <u>123-44971</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451079</u>	Type: <u>WELL</u>	API Number: <u>123-44972</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451080</u>	Type: <u>WELL</u>	API Number: <u>123-44973</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451081</u>	Type: <u>WELL</u>	API Number: <u>123-44974</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451082</u>	Type: <u>WELL</u>	API Number: <u>123-44975</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451083</u>	Type: <u>WELL</u>	API Number: <u>123-44976</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451084</u>	Type: <u>WELL</u>	API Number: <u>123-44977</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>451085</u>	Type: <u>WELL</u>	API Number: <u>123-44978</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

COGCC Comments

Comment	User	Date
Follow-up inspection will occur to ensure Operator has installed stormwater BMPs to meet Rule 1002.f. standards.	binschusc	08/09/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402573	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221635