

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/22/2017

Submitted Date:

08/29/2017

Document Number:

674200207**FIELD INSPECTION FORM**
 Loc ID 434526 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Mah, Steven		steven.mah@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
,		Cogcc.inspections@crestonepr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434525	WELL	DG	11/23/2014	SI	123-38225	Pratt 4G-29H-P168	DG
434527	WELL	DG	07/24/2017	LO	123-38226	Pratt 4D-29H-P168	DG
434528	WELL	DG	07/21/2017	LO	123-38227	Pratt 4F-29H-P168	DG
434529	WELL	DG	07/22/2017	LO	123-38228	Pratt 4E-29H-P168	DG

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	APPROX 32' SOUND WALLS SURROUND LOCATION		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	#		
Comment:	MUD CHILLER FOR ODOR MITIGATION		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type	Field Flare		
Comment:	NOT IN USE AT TIME OF INSPECTION		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: <u>434525</u>	Type: <u>WELL</u>	API Number: <u>123-38225</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434527</u>	Type: <u>WELL</u>	API Number: <u>123-38226</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434528</u>	Type: <u>WELL</u>	API Number: <u>123-38227</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434529</u>	Type: <u>WELL</u>	API Number: <u>123-38228</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

**Complaint**

Comment: Complaint #: 200443700

Complaint Received Aug 22, 2017

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date 8/22/2017 Time 1526 Hrs

Complaint Contacted:

Complaint #: 200443700

Complaint Received Aug 22, 2017

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date 8/22/2017 Time 1526 Hrs

Complaint Contacted:

Date: 8/22/2017 Time 1540 Hrs

Well Number#: Location #: 434526

Inspection Document #: 674200207

Nature of complaint: Odor

Field Inspector Actions:

On 8/22/2017, while driving in the area of Vista Ridge with CDPHE personnel Allie Bamber, we were contacted by a complainant in the area indicating she could smell a strong petroleum smell at her residence at 1909 Alpine Dr. in Vista Ridge. We drove to her residence where we were both able to smell a chemical odor which we believed was coming directly from the drilling rig. The odor detected appeared to be travelling with the wind which was approx. 0 to 4 mph out of the NW. The drilling rig is located approx. 240 yards to the NW of the complainants residence. Allie Bamber attempted to pull air samples at the time we detected the odors, those samples were sent into CDPHE for further analysis.

After smelling the odors we went to the Pratt location where we verified the odors detected off location were the odors coming from the drilling rig.

We advised Crestone we had detected the odors off location and we advised them to increase odor BMP's to control the odors from leaving location. Peter Santos Crestone representative advised his staff to increase odor mitigation fluid to control odors.

All information reviewed and site inspection information were submitted to the COGCC for further review.

We advised Crestone we had detected the odors off location and we advised them to increase odor BMP's to control the odors from leaving location. Peter Santos Crestone representative advised his staff to increase odor mitigation fluid to control odors.

Inspection was input at later date while waiting for CDPHE information.

All information reviewed and site inspection information were submitted to the COGCC for further review.

