

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2017

Submitted Date:

09/05/2017

Document Number:

675103916**FIELD INSPECTION FORM**Loc ID 438955 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 35080Name of Operator: GRAND MESA OPERATING COAddress: 1700 N. WATERFRONT PKWY BL 600City: WICHITA State: KS Zip: 67206**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent

General Comment:

This is a pre-drill, construction and stormwater inspection in response to Field Operations Notice doc. #401394133. Form 42 submitted by operator stated construction activities will conduct 9/5/2017. At time of inspection (~14:45), no equipment was on site and construction of the location had yet to commence.

Location Construction

Location ID: 438945 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Comment: No stormwater and sediment control BMPs were in place at time of inspections. Construction has yet to commence; Ensure that site specific stormwater and sediment control BMPs are installed with good engineering practices prior to, or at the start of, construction activities.**Corrective Action:** _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

COGCC Comments

Comment	User	Date
If start dates indicated by the submitted form 42 is not correct, operator should contact inspector or submit an updated notice to provide an accurate start date. If construction does not commence within 5 days from the stated start date, operator will need to submit a new form 42.	trujilloam	09/05/2017
A follow-up construction inspection will be conducted to determine compliance with COGCC requirements and standards.	trujilloam	09/05/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
675103917	Photo shows construction had not commenced	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4244228