

FORM
6

Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 401402461			
Date Received:			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>31257</u>	Contact Name: <u>Gene Fritzier</u>
Name of Operator: <u>FRITZLER RESOURCES INC</u>	Phone: <u>(970) 867-9388</u>
Address: <u>P O BOX 114</u>	Fax: <u>(866) 437-4804</u>
City: <u>FORT MORGAN</u> State: <u>CO</u> Zip: <u>80701</u>	Email: <u>gfritzier@bresnan.net</u>

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 COGCC contact: Email: _____

API Number <u>05-001-07673-00</u>	Well Number: <u>1-36</u>
Well Name: <u>APOLLO STATE</u>	
Location: QtrQtr: <u>SENE</u> Section: <u>36</u> Township: <u>2S</u> Range: <u>57W</u> Meridian: <u>6</u>	
County: <u>ADAMS</u> Federal, Indian or State Lease Number: <u>80-5114</u>	
Field Name: <u>APOLLO</u> Field Number: <u>2850</u>	

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.837439 Longitude: -103.708619

GPS Data:
 Date of Measurement: 06/04/2008 PDOP Reading: 2.5 GPS Instrument Operator's Name: Gene Fritzier, PE

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	5294	5296		CEMENT	-5030

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	114	130	114	0	
1ST	8+5/8	5+1/2	14	5,392	150	5,346	4,567	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1020 with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 5210 ft. to 5030 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 1000 ft. with 40 sacks. Leave at least 100 ft. in casing 900 CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at 164 ft. with 75 sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 75 sacks half in. half out surface casing from 164 ft. to 0 ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. of _____ inch casing Plugging Date: 03/01/2016
 *Wireline Contractor: Brand X Wireline LLC *Cementing Contractor: Yetter Well Service Inc.
 Type of Cement and Additives Used: Portland Cement Type 1 and 2: 14.5 # with 1/2 Sx of Chlorides
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Modified procedure to set cmt plug above perms and set CIBP and CICR at 1020 and 900 respectively was approved by Cogcc 2/25/2016.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Gene Fritzler
 Title: VP Date: _____ Email: gfritzler@bresnan.net

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401403432	WIRELINER JOB SUMMARY
401403435	WELLBORE DIAGRAM
401403438	SURFACE CASING CHECK
401403453	OTHER
401403466	CEMENT JOB SUMMARY

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)