

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401399327
Date Received:
09/11/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901839
Inspection Date: 08/01/2017 FIR Submit Date: 08/02/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306849

Location Name: PAYNE, EVELYN GAS UNIT F- N35N6W Number: 32SENE County: LA PLATA
Qtrqtr: SENE Sec: 32 Twp: 35N Range: 6W Meridian: N
Latitude: 37.259368 Longitude: -107.546769

FACILITY - API Number: 05-067-00

Facility ID: 269609

Facility Name: EVELYN PAYNE F Number: 2
Qtrqtr: SENE Sec: 32 Twp: 35N Range: 6W Meridian: N
Latitude: 37.259368 Longitude: -107.546769

CORRECTIVE ACTIONS:

1 CA# 89412

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 09/04/2017

Response: CA COMPLETED Date of Completion: 09/01/2017

BP Operations Technician made repairs to the pump jack to stop leak. Stained soils were cleaned up, placed in bags and transported to BP soil box to be remediated at IEI no disposal certificate is issued when placing soils

Operator Comment: into the soil box to provide. Small amounts of stained soils are placed in this containment box and the entire box is transported to IEI when full for remediation of the entire batch of soils. See attached documentation photos of work complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: BP has addressed the leaks of lube oil on the pump jack and the stained soils have been cleaned up and will be remediated at IEI. In addition BP has addressed the comment of paint peeling on the top of the tank by painting the tank and the containment ring. See attached photos of work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 9/11/2017 8:40:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401399327	FIR RESOLUTION SUBMITTED
401399339	Photos of work completion

Total Attach: 2 Files