

FORM
6
Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

CO

DNR

DE

ET

OE

ES

Replug By Other Operator

Document Number:
401393266

Date Received:
09/01/2017

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:10651

Contact Name:Robert Beecherl

Name of Operator:VERDAD RESOURCES LLC

Phone:(214) 2826419

Address:5950 CEDAR SPRINGS ROAD

Fax:

City:DALLASState:TXZip:75235

Email:bbeecherl@verdadoil.com

For "Intent" 24 hour notice required,Name:Montoya, JohnTel:(970) 397-4124

COGCC contact:Email:john.montoya@state.co.us

API Number05-123-07254-00

Well Name:UPRR 52 PAN AMWell Number:1

Location:QtrQtr:SESESection:7Township:1NRange:64WMeridian:6

County:WELDFederal, Indian or State Lease Number:

Field Name:WILDCATField Number:99999

☒ Notice of Intent to Abandon

☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude:40.060759Longitude:-104.587113

GPS Data:
Date of Measurement:08/18/2017PDOP Reading:1.5GPS Instrument Operator's Name:Randy Jakel

Reason for Abandonment:☐ Dry☐ Production Sub-economic☐ Mechanical Problems

☒ Other Re-Entry to Re-Plug

Casing to be pulled:☐ Yes☐ NoEstimated Depth:

Fish in Hole:☐ Yes☐ NoIf yes, explain details below

Wellbore has Uncemented Casing leaks:☐ Yes☐ NoIf yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	211	30	248	0	CALC
OPEN HOLE	7+7/8			8,010	170	7,903	7,613	CALC

Date Run: 9/18/2017 Doc [#401393266] Well Name: UPRR 52 PAN AM 1

Page 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 75 sks cmt from 6500 ft. to 6300 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set 40 sks cmt from 1200 ft. to 1100 ft. Plug Type: OPEN HOLE Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 260 ft. to 160 ft. Plug Tagged: ☒

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set 0 sacks in rat hole Set 0 sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: _____
of _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Robert Beecherl

Title: Operations Engineer Date: 9/1/2017 Email: bbeecherl@verdadoil.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 9/18/2017

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 3/17/2018

COA Type	Description
	<p>Bradenhead:</p> <p>Prior to initiation of plugging operations, a Bradenhead test shall be performed. Form 17 shall be submitted within 10 days. If there is 25 psi or greater pressure on the Bradenhead, or flowed any liquids from the Bradenhead, collect samples. See COGCC website - Operator Guidance - Bradenhead Testing and Reporting Instructions, Appendix A: Liquid and Gas Sampling.</p>
	<p>Note changes to submitted form.</p> <p>1) Provide 48 hour notice of MIRU via electronic Form 42.</p> <p>2) If not possible to reach 6500', as proposed for the first cement plug (75 sks at 6500-6300'), set 75 sks cement in shale as deep as possible (2500' minimum). Tag after WOC to confirm top of plug.</p> <p>3) Set 40 sk cement plug at 1200-1100' (Fox Hills).</p> <p>4) Shoe plug: Tag plug 50' above surface casing shoe, or cement to surface.</p> <p>5) Surface plug: Cement from 50' to surface.</p> <p>6) Properly abandon flowlines per Rule 1103. File Form 42 when done.</p> <p>7) Abandoned well marker shall be inscribed with the well's legal location, well name and number, and API Number (Rule 319.a.5).</p>

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401393266	FORM 6 INTENT SUBMITTED
401393335	LOCATION PHOTO
401393384	PROPOSED PLUGGING PROCEDURE
401393450	WELLBORE DIAGRAM
401393475	SURFACE OWNER CONSENT

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Agency	Zones: Erased information as no zones were completed.	09/18/2017
Public Room	Document verification complete 11/19/15	09/06/2017

Total: 2 comment(s)