

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401411336

Date Received:

09/22/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

Inspections, All

SanJuanCOGCC@bp.com

Fischer, Alex

alex.fischer@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901835

Inspection Date: 08/01/2017

FIR Submit Date: 08/02/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325654

Location Name: EVELYN PAYNE GAS UNIT A- Number: 32SEnw County: LA PLATA
N35N6W

Qtrqtr: SEnw Sec: 32 Twp: 35N Range: 6W Meridian: N

Latitude: 37.261418 Longitude: -107.554834

FACILITY - API Number: 05-067- -00 Facility ID: 215173

Facility Name: EVELYN PAYNE A Number: 1

Qtrqtr: SEnw Sec: 32 Twp: 35N Range: 6W Meridian: N

Latitude: 37.261418 Longitude: -107.554834

CORRECTIVE ACTIONS:

1 CA# 89400

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 09/04/2017

Response: CA COMPLETED

Date of Completion: 08/30/2017

On 8/23/17 an Operation Technician performed repairs to the oil lift controller and oil lift equipment to address the leak on the equipment and on 8/30/17 the stained soils were manually removed from location and deposited into

Operator Comment: the BP soil box for remediation at IEI in Farmington NM. The soil box is utilized for stained soils and is remediated in batches therefore, there is no waste disposal certificate to provide on this stained soil. See attached photos of work completed.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: On 8/23/17 an Operation Technician performed repairs to the oil lift controller and oil lift equipment to address the leak on the equipment and on 8/30/17 the stained soils were manually removed from location and deposited into the BP soil box for remediation at IEI in Farmington NM. The soil box is utilized for stained soils and is remediated in batches therefore, there is no waste disposal certificate to provide on this stained soil. See attached photos of work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 9/22/2017 12:58:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
|-------------------------------|---------------------------|

| | |
|-----------|-----------------------|
| 401411355 | Work performed photos |
|-----------|-----------------------|

Total Attach: 1 Files